


# MERIT Primary Containment Inspection


Van Graves

MERIT Video Conference  
October 13, 2010





# Mercury Primary Containment Inspection 17 Aug - Viewport 2

- Sapphire windows removed
- No obvious surface damage noted
- Higher quality photographs to be obtained



Sapphire Window Gasket




Mercury Beads

# New Photographs Taken 10 Sept With 35mm Camera & Macro Lens



Setup





Snout Orientation –  
Beam from Right  
Top of Container is Up




# Viewport 2 Upstream Side

- General surface appearance is uniform






# Viewport 2 Upstream Side Close-Ups









# Viewport 2 downstream side

- Raw material labeling intact





# Viewport 2 Top








# Viewport 2 Bottom





# Other Viewports Have Similar Images



# Primary Containment Microscopic Inspection

- Dissection of chamber around viewport 2
  - Might require purchase of dedicated tool due to radiation & Hg issues
  - Would also allow sectioning of mercury nozzle piping
- Decontamination of pieces (includes sapphire viewports)
- Inspection with SNS scanning electron microscope
- Cost estimate: \$25k





# Observations

- Surface appearance consistent throughout interior of primary containment – standard, un-machined surface texture
- Higher resolution images do not support theory of mercury bead pitting, at least on a macroscopic level
- Further investigation possible by sectioning chamber, decontaminating and viewing pieces with microscope