

Hole in the bottom of the SS Snout



Clearing the Secondary Volume

The scavenger pump attached to the secondary volume



Confirming no Hg vapor exiting

Short in the Primary Heater Tape



Damaged Heater Tape



Preparing the Primary for new Heater Tapes

